

This Page Is Inserted by IFW Operations
and is not a part of the Official Record

BEST AVAILABLE IMAGES

Defective images within this document are accurate representations of the original documents submitted by the applicant.

Defects in the images may include (but are not limited to):

- BLACK BORDERS
- TEXT CUT OFF AT TOP, BOTTOM OR SIDES
- FADED TEXT
- ILLEGIBLE TEXT
- SKEWED/SLANTED IMAGES
- COLORED PHOTOS
- BLACK OR VERY BLACK AND WHITE DARK PHOTOS
- GRAY SCALE DOCUMENTS

IMAGES ARE BEST AVAILABLE COPY.

**As rescanning documents *will not* correct images,
please do not report the images to the
Image Problem Mailbox.**

INLET MANIFOLD
1124 P62225 (67634) 0301710.0
Appn. No 0301710.0

FIG. 1.




FIG. 2.





FIG. 3.



A 00804

PL 2225 (6763t)
Appl. No. 0501710.0

FIG. 4.




FIG. 5.









FIG. 6.



A 00805


FIG. 7.3
3/24
P62225 (67634)
Appn. No. 0301710.0



A 00806

PL2225 (67634)
Appn. No 0501710.0
4/24

FIG. 11.



A 00807

P62225 (67634)
5/24 Appn. No. 0501110.0

FIG. 12.




FIG. 13.




FIG. 14.





FIG. 15.



A 00808

FIG 2225 (67634)
Appn. No. 0301710.0

6/24

FIG. 16.





FIG. 17.



A 00809

FW2225 (67634)
Aprin. No 0301710.0

7/24




FIG. 18.

A 00810

F62225 (67634)
Appn. No. 0501710.0

8124





FIG. 20.



A 00811

P62225 (67434)
Appn. No. 0501710.0
9/25

FIG. 21.




FIG. 22.





FIG. 23.



A 00812

P 62225 (67634)
Appl. No. 0301710.0

10/24

FIG. 24.




FIG. 25.




FIG. 26.




FIG. 27.






FIG. 28.



A 00813

P62225 (67634)
Appn. No. 0301710.0

11/24



A 00814

F62225 (67634)
Appn. No. 0301710.0

12/24

FIG. 30.




FIG. 32.




FIG. 31.





FIG. 33.



A 00815

P62225 (67634)
Appn No. 0301710.0

13/24





FIG. 34.

A 00816

FIG. 2225 (67634)
Appn. No. 0301710.0

14/24




A 00817

P62225 (67634)
Appn. No. 0501710.0

15/24

FIG. 36.




A 00818

FIG. 2225 (67634)
Appn No. 0301710.0

16/24

FIG. 37.




A 00819

P62225 (67634)
Appn. No. 0501710, 0

17/24

FIG. 38.




A 00820

P62225 (67634)
Appn. No. 0501710.0

18/24

FIG. 39.




A 00821

F62225 (67634)
Aprin Nr. 0501710.0


19/24

FIG. 40.



A 00822

P62225 (67634)
Appn. No. 0301710.0
20/24




A 00823

FIG 2225 (67634)
Appn. No. 0301710.0

21/24


FIG. 42.



A 00824

P62225 (67634)
Appn. No. 0301710.0

22/24



A 00825

P62225 (6763t)
Appn. No. 0301710.0

23/24

FIG. 44a.





FIG. 44b.




A 00826

P62225 (67634)
Appn. No. 0301710.0

24/24

FIG. 45.



A 00827